



North Bank Playground

Completed By: Patrick McCord

Date of Report: June 18, 2020

Time of Observation: 1:00 PM

1. WEATHER							
	Clear	PM	Calm		<10 deg		61-70 deg
PM	P/Cloudy		Slight Breeze		11-20 deg	PM	70-80 deg
	Overcast		Moderate Winds		21-32 deg		80-90 deg
	Rain		Windy		33-45 deg		91-99 deg
	Smokey		Very Windy +35mph		45-60 deg		100+
	Snow						
2. CONSTRUCTION ACTIVITY							
Area	Observation						
Site	Parking lot walls have been poured and stripped (east side); north walls have been backfilled. Pipe and gravel wrap has been installed at storm channel (east of the large shelter). South skate park wall being formed; subgrade base has been shaped east and west sides. Rock fill has been placed inside skate park storm channel. Sidewalk has been removed along Washington St.; subgrade being prepped for new sidewalk. Subgrade being prepped for curb wall at southeast corner of parking lot.						
Building	Concrete slab being placed and finished (east side); west side has been sawcut.						
3. LABOR							
Contractor	# Of Workers	Contractor	# Of Workers	Contractor	# Of Workers	Contractor	# Of Workers
T LaRiviere	16		0		0		0
Budinger	0						
4. EQUIPMENT ON SITE							
Type of Equipment	#	Type of Equipment	#	Type of Equipment	#	Type of Equipment	#
Compaction roller	1	Dozer	0	Track hoe	2		
Terex dumptruck	1	Front loader	1	Water truck	1		
Bobcat	1	Extended forklift	1	Concrete pump truck	0		
Grader	1	Mini track hoe	1	Extended manlift	1		
5. TPZ							
•							
6. DELIVERIES & CONDITIONS Note time and type of delivery							
•							
7. FIELD DISCUSSIONS OR NOTES (provide bulleted list of discussions, directions or decisions)							
•							
8. SCHEDULE REVIEW							
•							
9. PROJECT PHOTOGRAPHS							
• See pictures below:							



North Bank Playground


Completed By: Patrick McCord

Date of Report: June 18, 2020

Time of Observation: 1:00 PM



#1 View from cliff east side of the cliff (facing south).



#2 View from east side of the cliff (facing west).



#3 Storm channel liner/membrane and piping.



#4 East section of skate park.



#5 West section of skate park.



#6 M&O Building foundation (view from southwest corner)



7 East side site retaining walls.



#8 O&M Building (facing south).



#9 Sidewalk subgrade along Washington Street.